U.S. Department of Veterans Affairs **Revision Number: 8** Oklahoma City, OK - Steel Moment Frame, Twelve-Story Hospital Building Revised on 08/26/2021 **Building No: 1** Revised by: Abazarsa/Celebi 25 NSMP Station No: 7413 171'-10" 41'-8" **Third Floor** 19'-5" 59'-5" 166' **Ground Floor** 26 538'-8" Seventh Floor Roof 10'-11" 9th Floor 11'-7" 11'-11" 边区 7th Floor 11' 6th Floor 11'-11" ក្រុ 179'-3" **Fourth Floor** 5th Floor ∐ 20'-9" 12'-7" 🖔 ceiling of 3rd floor 81'-9" 122'-8" 75'-2" ceiling of basement ceiling of ground floor 11' 11' 2nd Floor 11' **Eighth Floor** 1st Floor **First Floor Elevation View Looking Reference North** ceiling of 4th floor The vertical to horizontal scale factor is 4 Fifth Floor N_{ref} 160'-6" 39 2" expansion joint **→**40 **Ninth Floor** 108'-4' Basement ceiling of 1st floor Structural Reference 131'-8" Orientation: 0° ceiling of 5th floor ceiling of 8th floor 83'-11 **Second Floor** Sixth Floor 197'-9" 145'-3" 46 penthouse roo 35'-10" Roof 97'-4" 124'-6" 195'-1" Department of Veterans Affairs SENSOR LOCATIONS