






Lancaster 3-story Office Bldg  
CSMIP Station No. 24517

SENSOR LOCATIONS



N  
N<sub>ref</sub>  
Structure Reference  
Orientation: N<sub>ref</sub> = 25°




Note: Sensors 14 & 15  
Added During 2024  
Reinstrumentation

Reinstrumented: 02/14/2024  
Diagram: 04/05/2024 rev.

Lancaster - 3-story Office Bldg  
(CSMIP Station No. 24517)


SENSOR LOCATIONS



S/N Elevation


Roof  
3rd Floor  
2nd Floor  
Ground Floor

Reinforced Masonry  
Shear Walls




Roof Plan


N  
N<sub>ref</sub>  
Structure Reference  
Orientation: N<sub>ref</sub> = 25°



3rd Floor Plan



Ground Level Plan



2nd Floor Plan