



Fremont - 3-story Hospital (CSMIP Station No. 57643)

SENSOR LOCATIONS




N_{ref}


N

Structure Reference
Orientation: $N_{ref} = 33^\circ$


► Relative Displacement Sensors
(22-UP, 23-EW, 24-NS)




Foundation (Below Isolator) Plan




Ground Floor (Above Isolator) Plan



Penthouse Roof Plan



Fourth Floor (Roof) Plan



Third Floor Plan