



San Francisco - 7-story Hospital (CSMIP Station No. 58574)

SENSOR LOCATIONS



Foundation (Below Isolator) Plan

Penthouse Roof
Roof
Seventh Floor


Fourth Floor

First Floor


Basement 2
Foundation

Free-Field
(CSMIP Station 58575)


Structure Reference
Orientation: $N_{ref} = 356^\circ$




First Floor Plan




Basement 2 (Above Isolator) Plan



Roof Plan



Seventh Floor Plan



Fourth Floor Plan

▲ Relative Displacement Sensors
(21-UP, 22-UP, 23-EW, 24-NS)

Installed: 7/25/2014
Diagram: 10/14/2014