


Castro Valley - 1-story Hospital
(CSMIP Station No. 58661)

SENSOR LOCATIONS



Structure Reference
Orientation: $N_{ref} = 10^\circ$

