






Santa Rosa - 4-story Hospital

(CSMIP Station No. 68669)

SENSOR LOCATIONS



N, N_{ref}
Structure Reference
Orientation: $N_{ref} = 360^\circ$



Installed: 10/07/93
Diagram: 10/03/18 Rev.